


Date: Wednesday, 06/08/2008 10:46:33 AM
 User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: D3446-041
Job Number	: 40796		
Estimate Number	: 10804		
P.O. Number	:	Part Number	: D34461
This Issue	: 06/08/2008	S.O. No.	:
Prsht Rev.	: NC	Drawing Number	: R08-054 (-50)
First Issue	: / /	Project Number	:
Previous Run	: 00015	Drawing Revision	:
	Type : PURCHASED PARTS	Material	:
Written By	: 	Due Date	: 06/08/2008
Checked & Approved By	:	Qty:	1
Comment	:	Um:	Each

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	D34461	Left Buckle Harness
-----	--------	---------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Left Buckle Harness

Qty 15 D3446-1

Qty 10 B25175.

Qty 5 B?????? unknown

4x SSP3005

5x SSP5106

2x SSP1105

1x SSP3106

2 of 12 have missing springs in the clip.

2.0	D344611	Left Buckle Harness
-----	---------	---------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Left Buckle Harness


Qty 8 original B25176

4x SSP5106

3x SSP3005

1x SSP1105

Qty 2 have missing springs in the clip.

3.0	D344613	Right Buckle Harness
-----	---------	----------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Right Buckle Harness

Exact B# is unknown. No tag left on buckle.

Qty 4. 2 of 4 have missing springs in the clip.

Date: Wednesday, 06/08/2008 10:46:33 AM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D3446-041

Job Number: 40796

Part Number: D34461

Job Number:



Seq. #:

Machine Or Operation:

Description :

4.0

QC

QUALITY CONTROL



Comment: QUALITY CONTROL

Parts are quarantined to be returned to supplier for replacement.

Parts are scrap.

08/10/07

5.0

QC21

FINAL INSPECTION/W/O RELEASE



08/10/09

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



08/10/07